Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	772	(228/2.1,112.1).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/07/20 16:49
L2	7421	(friction near (stir or agitation or plug or plunge) or stir or fsw) and weld\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/20 16:49
L3	376	1 and 2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/20 16:49
L4	23	3 and control\$4 and (control\$4 or maintain\$4) near (torque or plunge or distance or height)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2005/07/20 16:55
L5	28	1 and control\$4 and (control\$4 or maintain\$4) near (torque or plunge or distance or height)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/20 16:55
L6	132	2 and control\$4 and (control\$4 or maintain\$4) near (torque or plunge or distance or height)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/20 16:55
L7	4	(5 or 6) and load same factor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/20 16:56
L8	0	4 and load same factor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/07/20 16:56